

## model PBA7

Valve Button

### **FEATURES & BENEFITS**

### **OPTIONS**


For more information, visit www.hawsco.com or call (888) 640-4297.



### **SPECIFICATIONS**

Model PBA7 push button assembly is used with push button valve 5874, is made of polished chrome-plated brass, and includes the push button with front adjusting screw, operator, round locknut, snap ring and wave washer. This model is used on drinking fountains with front recessed push buttons and for drinking fountains with thick walls.

**APPLICATIONS** 



## MODEL VRK5874 & VRK5874HF- VALVE REPAIR KITS INCLUDE THESE ITEMS (SEE SHEET 3 OF 3 FOR REPLACEMENT INSTRUCTIONS)


# INSTALLATION/REPLACEMENT INSTRUCTIONS FOR 5874PBF

- FOLLOW INSTRUCTIONS CAREFULLY ON O&M MANUAL (PAGE 2 OF 7) WHEN REMOVING OLD VALVE. NOTE: SEE PARTS BREAKDOWN (PAGE 4 OF 7) FOR ADDITIONAL NOTES
- 2) VERIFY THAT LOCK NUT, FIBER, AND RUBBER WASHERS ARE POSITIONED SLIGHTLY PAST MIDWAY OF THREADS ON NEW VALVE BODY
- 3) INSERT VALVE INTO BRACKET FROM INSIDE AND PUSH FORWARD ABOUT 1"
- 4 THREAD LARGE RING NUT ONTO VALVE BODY, APPROXIMATELY 1" INTO VALVE
- 5 PLACE WAVE WASHER INSIDE OF FLANGED PUSH BUTTON ASSEMBLY (MUST ALWAYS BE IN PLACE).
- 6 APPLY ONE (1) DOT OF LOCTITE 222MS, ON THE FEMALE THREADS OF BUTTON ASSEMBLY CAUSE THREADS TO LOCK VERY TIGHTLY, MAKING REPAIRS DIFFICULT. LEAVING THE FIRST AND LAST THREADS FREE. (FIGURE 1). CAUTION: EXCESS LOCTITE CAN
- \*\*7) THREAD FLANGED PUSH BUTTON ASSEMBLY ON VALVE UNTIL WAVE WASHER MAKES SLIGHT CONTACT WITH STEM OF CARTRIDGE. CAUTION: DO NOT HAND-TIGHTEN.
- 8 UNTHREAD RING NUT FORWARD UNTIL IT STOPS FLUSH WITH PUSH BUTTON ASSEMBLY

9 OF

<u>PAGE</u>

- 9 PUSH VALVE BACK TOWARD THE INSIDE OF BRACKET AND TIGHTEN LOCKNUT (SEE ILLUSTRATION ABOVE).
- 10) TIGHTEN PUSH BUTTON ASSEMBLY USING UNIVERSAL SPANNER WRENCH PROVIDED WITH MODEL 5874PBF.
- OVERTIGHTENING WILL PRE-ACTUATE VALVE AND CAUSE WEEPAGE, WHILE NOT ENOUGH CONTACT BETWEEN WAVE WASHER AND STEM CAN CAUSE A LOW FLOW CONDITION



PAGE 5

OF 7

(FLUSH MOUNT APPLICATION ONLY) ASSEMBLED 5874PBF

SEE SHEET 2 OF 3 FOR 5874PB RECESSED MOUNT INSTRUCTIONS.




FIGURE 1

## NOTE!

BE SURE TO REMOVE ANY EXISTING FLOW THIS VALVE IS PRESSURE COMPENSATING CONTROL DEVICES. (MAY BE PRESENT IN FITTING OR SPUD)




(775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWSCO.COM WEBSITE: WWW.HAWSCO.COM 1455 KLEPPE LANE SPARKS, NEVADA 89431

5874PB/5874PBF/VRK5874/VRK5874HF/ )002077650.D

PBA6/PBA6C/PBA7/PBA7C

©2023 Haws Corporation - All Rights Reserved. HAWS®and other trademarks used in these materials are the exclusive property of Haws Corporation



## ASSEMBLED 5874PB

PAGE 6

(RECESSED MOUNT APPLICATION SHOWN)

SEE SHEET 1 OF 3 FOR FLUSH MOUNT INSTRUCTIONS

## INSTALLATION/REPLACEMENT INSTRUCTIONS FOR 5874PB \*\*\* MODEL VRK5874 & VRK5874HF- VALVE REPAIR KITS INCLUDE THESE ITEMS (SEE SHEET 3 OF 3 FOR REPLACEMENT INSTRUCTIONS)

- 1) FOLLOW INSTRUCTIONS CAREFULLY ON O&M MANUAL (PAGE 2 OF 7) WHEN REMOVING OLD VALVE. NOTE: SEE PARTS BREAKDOWN (PAGE 4 OF 7) FOR ADDITIONAL NOTES
- 2) VERIFY THAT LOCK NUT, FIBER WASHER, AND RUBBER WASHERS ARE POSITIONED TOWARD BOTTOM END OF THREADS ON NEW VALVE BODY
- INSERT VALVE INTO BRACKET FROM INSIDE, AND PUSH ALL THE WAY FORWARD SEE ILLUSTRATION ABOVE
- [4] THREAD RING NUT ONTO VALVE BODY, AS FAR IN AS POSSIBLE, TOWARD FRONT OF FOUNTAIN. NOTE: IF REPLACING A 5871 OR 5872 SERIES VALVE, YOU MAY HAVE TO CONTACT HAWS TECHNICAL SUPPORT.
- 5 PLACE WAVE WASHER INSIDE OF PUSH BUTTON ASSEMBLY (MUST ALWAYS BE IN PLACE).
- 6 APPLY ONE (1) DOT OF LOCTITE 222MS, ON THE FEMALE THREADS OF BUTTON ASSEMBLY CAUSE THREADS TO LOCK VERY TIGHTLY, MAKING REPAIRS DIFFICULT. LEAVING THE FIRST AND LAST THREADS FREE. (FIGURE 1). CAUTION: EXCESS LOCTITE CAN
- \*\*7) THREAD PUSH BUTTON ASSEMBLY ON VALVE UNTIL WAVE WASHER MAKES SLIGHT CONTACT WITH STEM OF CARTRIDGE. CAUTION: DO NOT HAND-TIGHTEN
- ${f [8]}$  UNTHREAD RING NUT FORWARD UNTIL IT STOPS FLUSH WITH PUSH BUTTON ASSEMBLY.

O 9

<u>PAGE</u>

- 9 PUSH VALVE BACK TOWARD THE INSIDE OF BRACKET AND TIGHTEN LOCKNUT (SEE ILLUSTRATION ABOVE).
- 10) TIGHTEN PUSH BUTTON ASSEMBLY USING UNIVERSAL SPANNER WRENCH PROVIDED WITH MODEL 5874PB.
- OVERTIGHTENING WILL PRE-ACTUATE VALVE AND CAUSE WEEPAGE, WHILE NOT ENOUGH CONTACT BETWEEN WAVE WASHER AND STEM CAN CAUSE A LOW FLOW CONDITION



**\* THIS ALSO APPLIES** 

TO PBA7/PBA7C

FIGURE

## NOTE

BE SURE TO REMOVE ANY EXISTING FLOW THIS VALVE IS PRESSURE COMPENSATING CONTROL DEVICES. (MAY BE PRESENT IN FITTING OR SPUD)



SPARKS, NEVADA 89431 1455 KLEPPE LANE

(775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWSCO.COM WEBSITE: WWW.HAWSCO.COM )002077650.D

5874PB/5874PBF/VRK5874/VRK5874HF/ PBA6/PBA6C/PBA7/PBA7C

©2023 Haws Corporation - All Rights Reserved. HAWS®and other trademarks used in these materials are the exclusive property of Haws Corporation


## FIGURE 1

## REPLACEMENT INSTRUCTIONS FOR VRK5874/VRK5874HF

- 1) FOLLOW INSTRUCTIONS CAREFULLY ON O&M MANUAL (PAGE 2 OF 7) WHEN REMOVING VALVE. NOTE: SEE PARTS BREAKDOWN (PAGE 4 OF 7) FOR ADDITIONAL NOTES
- 2 REMOVE FRONT PUSH BUTTON (WITH WAVE WASHER INSIDE) AND RETAINING NUT WITH VRK5874HF KITS) THE UNIVERSAL SPANNER WRENCH (PN 0006983506 - NOT SUPPLIED WITH VRK5874 AND
- PULL EXISTING CARTRIDGE ASSEMBLY WITH GASKET SCREEN OUT.
- 4 WHEN INSERTING NEW CARTRIDGE ASSEMBLY WITH GASKET SCREEN, FOLLOW THESE IMPORTANT STEPS:
- ASSEMBLY INTO THE VALVE BODY MAKE SURE THERE IS NO DEBRIS IN THE VALVE BODY BEFORE INSERTING THE CARTRIDGE
- SLIGHTLY INTO PLACE. CARTRIDGE IS ALSO PROPERLY ALIGNED WITH SMALLER OPENING IN VALVE BODY BY TURNING ALIGN STRAINER WITH LARGE HOLE IN THE VALVE BODY AND ENSURE THE OUTLET PORT ON
- CONFIRM CARTRIDGE HAS BOTTOMED OUT PROPERLY BEFORE INSTALLING RETAINING NUT.
- (CAUTION: WHEN REPLACING CARTRIDGE W/GASKET ASSEMBLY, DAMAGE CAN OCCUR IF NOT CHECK FOR LEAKS. THREAD RETAINING NUT UNTIL IT CONTACTS THE CARTRIDGE, THEN TIGHTEN 1-1/4 TURN FARTHER,
- PROPERLY RE-INSTALLED)
- 5 PLACE WAVE WASHER (EXISTING OR NEW) INSIDE OF PUSH BUTTON ASSEMBLY (MUST ALWAYS BE IN PLACE).

PAGE

- 6 APPLY ONE (1) DOT OF LOCTITE 222MS, ON THE FEMALE THREADS OF EXISTING BUTTON ASSEMBLY CAUSE THREADS TO LOCK VERY TIGHTLY, MAKING REPAIRS DIFFICULT. LEAVING THE FIRST AND LAST THREADS FREE. (SEE FIGURE 1). CAUTION: EXCESS LOCTITE CAN
- SLIGHT CONTACT WITH STEM OF CARTRIDGE. CAUTION: DO NOT HAND-TIGHTEN
- 8) TIGHTEN EXISTING PUSH BUTTON ASSEMBLY USING UNIVERSAL SPANNER WRENCH (PN 0006983506 NOT SUPPLIED WITH VRK5874 AND VRK5874HF KITS).
- \*\* OVERTIGHTENING WILL PRE-ACTUATE VALVE AND CAUSE WEEPAGE, WHILE NOT ENOUGH CONTACT BETWEEN WAVE WASHER AND STEM CAN CAUSE A LOW FLOW CONDITION



**PAGE** 

7

## \*\*\* MODEL VRK5874 & VRK5874HF- VALVE REPAIR KITS INCLUDE THESE ITEMS

## NOTE

BE SURE TO REMOVE ANY EXISTING FLOW THIS VALVE IS PRESSURE COMPENSATING CONTROL DEVICES. (MAY BE PRESENT IN FITTING OR SPUD)



MODEL(S)

(775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWSCO.COM WEBSITE: WWW.HAWSCO.COM SPARKS, NEVADA 89431 1455 KLEPPE LANE

5874PB/5874PBF/VRK5874/VRK5874HF/ )002077650.D

PBA6/PBA6C/PBA7/PBA7C

©2023 Haws Corporation - All Rights Reserved. HAWS® and other trademarks used in these materials are the exclusive property of Haws Corporation