



NOTES:

1. THE HANDLE/STEM REPAIR KIT FOR THIS MODEL IS: 5851LFHST.
2. THE VALVE REPAIR KIT FOR THIS MODEL IS: 5800VRKT.




Haws Corporation
 INFO FAX : 1-888-FAX-HAWS (1-888-329-4297)
 1455 Kleppe Ln, Sparks NV, 89431
 Phone: 775-359-4712 Fax: 775-359-7424
 Haws Ag, Bachweg 3, CH-3401 Burgdorf Switzerland
 Haws Mfg Pte Ltd 74 Sungai Kadut Loop Singapore 729531
 e-mail: Haws@hawsco.com website: www.hawsco.com

| | | | | | |
|------------------------------------|-------------|----------|-------------------------|------|----------|
| FOR NO. | REVISED PER | DATE | BY | DATE | APPROVED |
| ECN: 4010 | HM | 07/19/95 | | | |
| MODEL(S): 5851LF | | | INFO FAX DOC #: 2585153 | | |
| DRAWING NUMBER: 11884A00 | | | SCALE: 1:1 | | |
| DRAWING TYPE: INSTALLATION/FABRICK | | | SIZE: A SH: 1 OF 1 | | |