

NOTES:

- 1 | 5874PBF (ITEM 2) INCLUDES VRK5874 CARTRIDGE ASSEMBLY (ITEM 3) AND PBA6 FLANGED PUSH BUTTON (ITEM 4).
- 2 ENSURE TUBE IS DISCONNECTED FROM PUSH BUTTON VALVE BODY PRIOR TO REMOVAL. APPLY ONE DROP OF LOCTITE 222MS TO NOZZLE THREADS PRIOR TO FASTENING BACK ONTO BUBBLER HEAD. RE-ATTACH TUBE TO VALVE.


	ITEM	DESCRIPTION	PART NO.
	1	BUTTON, PUSH, FLANGED, PCP W/ VALVE	5874PBF
	2	VALVE REPAIR KIT	VRK5874
	3	PUSH BUTTON ASSY	PBA6
	4	BUBBLER HEAD ASSY, PCP	5703M
	5	STRAINER, WASTE ASSY	6462
	6	TRAP	0005982900
*	7	MOUNTING PLATE	6717
	8	BOTTOM PLATE	PBM1107

** REQUIRED - SOLD SEPARATELY





ROTATED 90° INTO VIEW



PARTS BREAKDOWN



1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWSCO.COM

MODEL(S) 0002080223

1117L

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.