


ITEM	DESCRIPTION	PART NO.
1	STRAINER	0005624292
2	BUBBLER HEAD, PCP (STYLE A OR STYLE B)	5705
3	BUTTON, PUSH, RECESSED W/VALVE	5874PB
4	VALVE REPAIR KIT	VRK5874
5	BUTTON ASSY, PUSH, 5874	PBA7
6	DRIVER, NOZZLE .25 HEX	0002082253

NOTES:

- 1 ITEM 3, 5874PB PUSH BUTTON, INCLUDES ITEM 4, VRK5874 VALVE REPAIR KIT, AND ITEM 5, PBA7 PUSH BUTTON ASSY.
- 2 ENSURE TUBE IS DISCONNECTED FROM PUSH BUTTON VALVE BODY PRIOR TO REMOVAL. APPLY ONE DROP OF LOCTITE 222MS TO NOZZLE THREADS PRIOR TO FASTENING BACK ONTO BUBBLER HEAD. RE-ATTACH TUBE TO VALVE.



**FOUNTAIN COULD HAVE EITHER STYLE
DETAIL A
ROTATED 90° INTO VIEW**

PARTS BREAKDOWN

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.

		Haws [®]		1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWS.CO.COM WEBSITE: WWW.HAWS.CO.COM	
				ECN NO. REVISED PER BY ECN: 5274 VWC	MODEL(S) 3380/3380G
DRAWN D. OLLOM	DATE 11-25-95	CHKD VWC			
APPROVED FV	DATE 02/23/18	SCALE: 1:8	DRAWING TYPE: PARTS BREAKDOWN	SIZE: A	SHEET 1 OF 1