



NOTES:

- 1 5874PB INCLUDES VRK5874 CARTRIDGE ASSEMBLY AND PBA7 RECESSED PUSH BUTTON.
- 2 ENSURE TUBE IS DISCONNECTED FROM PUSH BUTTON VALVE BODY PRIOR TO REMOVAL. APPLY ONE DROP OF LOCTITE 222MS TO NOZZLE THREADS PRIOR TO FASTENING BACK ONTO BUBBLER HEAD. RE-ATTACH TUBE TO VALVE.
- 3 **IMPORTANT:** IF HOSE BIB IS USED ALONG WITH A SAND TRAP, IT MUST BE USED WITH SAND TRAP 6611. CANNOT OFFER HOSE BIB AS OPTION WITH SAND TRAP 6635. IF HOSE BIB IS PURCHASED, ACCESS PLATE, 0004521763, MUST BE USED.

SPANNER WRENCH
0006983506



MODEL 6250LF BIB FAUCET
(OPTIONAL)

3

5705
BUBBLER HEAD

STRAINER
0005624292

1 PBA7 PUSH
BUTTON ASSY

1 VRK5874 VALVE
REPAIR KIT

5874PB VALVE 1

ACCESS PLATE
0004521763
(OPTIONAL)

MUST BE USED WITH 6250LF

6635
SAND TRAP
W/MOUNTING PLATE
(OPTIONAL)



0002082253
(OPTIONAL)
FOR REMOVAL
OF NOZZLE
WITH TUBE

5705LAMIN
(OBSOLETE -
SHOWN FOR
REFERENCE
ONLY.)

STYLE A
(TUBING CONNECTS
TO ELBOW)

STYLE B
(TUBING CONNECTS TO
INSERT ASSY)

PARTS BREAKDOWN

FOUNTAIN COULD HAVE EITHER STYLE

DETAIL A
ROTATED 90° INTO VIEW

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.

		1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWS.CO.COM WEBSITE: WWW.HAWS.CO.COM	
ECN NO.	REVISED PER	BY	MODEL(S)
	ECN: 5438	FV	3511
DRAWN	DATE	CHKD	PART NUMBER
P.M.	05-03-00	DP	0002074001
APPROVED	DATE		REVISION
IR	12/09/19		18
SCALE: 1:4		DRAWING TYPE: PARTS BREAKDOWN	
SIZE: A		SHEET 1 OF 1	