




REPLACEMENT PARTS




**MODEL 5881PBA
BUTTON ASSEMBLY
(FR MODELS)**




**MODEL 5703M
BUBBLER HEAD**



**0510001030
HEX BIT,
PINNED, 5/32"**




**0006983506
SPANNER WRENCH
(NON FR MODELS)**



**0510001029
HEX BIT,
PINNED, 1/8"**


OPTIONAL ACCESSORIES




**MODEL MTG.3600
INSTALLATION AID**

**3602FR
MODULAR OUTDOOR FOUNTAIN SYSTEM**


PARTS BREAKDOWN

		1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWSO.COM WEBSITE: WWW.HAWSO.COM	
ECN: 5652	REV. ECN: 5822	BY: JU	MODEL(S) 3602FR
DRAWN: DHP	DATE: 6/11/20	CHKD: BJM	PART NUMBER 0580001169
APPROVED: FV	DATE: 07/12/22	SCALE: 1:2	REVISION 3
WHEN ORDERING PARTS, PLEASE SPECIFY PART NUMBER		DRAWING TYPE: PARTS BREAKDOWN	SHEET 1 OF 2


AVAILABLE SUB COMPONENT MODELS



MODEL 3671 PEDESTAL ARM ASSEMBLY




MODEL 3674 PEDESTAL ASSEMBLY



MODEL 3680FR* FOUNTAIN ASSEMBLY

(PUSH BUTTON SHOWN IS FOR REF. ONLY, ACTUAL PUSH BUTTON IS DIFFERENT STYLE)



MODEL 3690FR* BOTTLE FILLER ASSEMBLY


(PUSH BUTTON SHOWN IS FOR REF. ONLY, ACTUAL PUSH BUTTON IS DIFFERENT STYLE)

**3602FR
MODULAR OUTDOOR
FOUNTAIN SYSTEM**

PARTS BREAKDOWN

*FR (FREEZE RESISTANT) MODELS REQUIRE THE USE OF SEPARATE FREEZE RESISTANT VALVES (NOT SUPPLIED). SEE INSTALLATION DRAWINGS ON THE FOLLOWING PAGES FOR DETAILS.

WHEN ORDERING PARTS, PLEASE SPECIFY PART NUMBER

		1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWS.CO.COM WEBSITE: WWW.HAWS.CO.COM	
ECN: 5652	REV. ECN: 5822	BY: JU	MODEL(S) 3602FR
DRAWN: DHP	DATE: 6/11/20	CHKD: BJM	PART NUMBER 0580001169
APPROVED: FV	DATE: 07/12/22	SCALE: 1:16	REVISION 3
DRAWING TYPE: PARTS BREAKDOWN		SIZE: A	SHEET 2 OF 2